# Arkansas Department of Human Services Division of Child Care & Early Childhood Education Placement & Residential Licensing Unit

**Licensing Compliance Record** 

Agency Na Address: Licensing Date of Vis	Specialist: A Phone:	Mobiler d GRD	inds
STANDARD REVIEWED	DISCUSSION/OBSERVATION	COMPLIANCE	DATE
901000	Viewed Station I and Station 2 school and Gym buildings and all areas used by children:  Station I: Room 110 need mattress replaced  Station 2: Room 204 has hole in wall  Room 202 - Room has electrical outlet need up to Room 202 - Has hole in ceiling.  Room 209 - Has hole in ceiling and at floor bor Room 212 - Has hole in ceiling and at floor bor Room 213 - Has hole in ceiling.  Room 213 - Has hole in ceiling.  Room 220 - Window Seal Has chipped wood with Gym-Door is off-hinge.	43419 4019 1019 11019 11019	6/17/16 96/17/16 16/17/19
1) 0	GNING AS RECEIVING  DATE  LICENSING SPECIALIST	W 1	DATE

# Arkansas Department of Human Services Division of Child Care & Early Childhood Education Placement & Residential Licensing Unit

**Licensing Compliance Record** 

Agency Name: MODOLI COR TOWNST City Person In Charge: Town Mobiley								
Address:	Kitto + Cores-City, AR Phone:							
Date of Vis	Specialist: Atmosphine	1						
Date of Vis	Purpose of Visit: Ollion CN	L COICIDA	MIL					
	<u> </u>							
STANDARD REVIEWED	DISCUSSION/OBSERVATION	COMPLIANCE	DATE					
MEATEMED		DATE	CORRECTE					
	101							
	TAI							
	Discussed at visit that areasthare perling paint are being addressed by							
	Discussed in the likely have							
1	perfunt paintake perny adaressed by	_						
	Discussed that areas that have holes punched in walls are being addressed by facility.							
	1 account							
	Derussed that areas that have holes,							
YE	Durally lin units are being addressed							
	prenoued in vocal							
	by tachty							
80								
<u> </u>								
COMMENTS	of Person receiving form:		<u> </u>					
m	contact the harmon and							
DEDCON SI	MINO AS PEGENANO	) (0)	10/19					
DCCECE 52	SNING AS RECEIVING DATE LICENSING SPECIALIST		DATE					

## **Arkansas Department of Human Services** Division of Child Care and Early Childhood Education P.O. Box 1437, Slot S140 - Little Rock, AR 72203-1437

501-682-8590 - Fax: 501-683-6060 - TDD: 501-682-1550

## **521 Visit Compliance Report**

Licensee:

Woodridge Behavioral Care of Forrest City

Licensee Address:

603 KITTLE ROAD FORREST CITY, AR 72335

Licensing Specialist:

Fatima Stepps

Person in Charge:

Marcel Lue

**Monitor Visit Date:** 

6/10/2019

Purpose of Visit:

Psychiatric Residential Buildings and Grounds

#### Regulations Out of Compliance:

Regulation	Serious Violation	Discussion/Observation	Due Date	Correction	Corrected
R1010.1	No	Rooms 202,204,209,210,211,212,213,220 and	7/10/2019	Date	On Site
Date -	Gym r	ym needs repairs	77 10/2018		No
R913.5	No	Room 110 needs mattress replaced	6/30/2019		No
R1011.7	No	Rooms 202,204,209,210,211,212,213,220 and Gym needs repairs	7/10/2019		No
R911.6	No	Rooms 202, 204, 209, 210, 211, 212, 213, 220 and Gym needs repairs	7/10/2019		No
R910.1	No	Rooms 202, 204, 209, 210, 211, 212, 213, 220 and Gym needs repairs	7/10/2019		No

### Regulations Needing Technical Assistance:

No regulations needing technical assistance.

#### **Regulations Not Correctable:**

No regulations marked as not correctable.

Narrative:

www.arkansas.gov/dhs Serving more than one million Arkansans each year

7b3da082-528c-e911-b91c-a44cc8a079c4

### **Arkansas Department of Human Services**

Division of Child Care and Early Childhood Education

P.O. Box 1437, Slot S140 - Little Rock, AR 72203-1437 501-682-8590 - Fax: 501-683-6060 - TDD: 501-682-1550

Viewed Station 1 and Station 2, School and Gym bulldings and all areas used by children:

Station 1: Room 110 needs mattress replaced.

Station 2: Room 204 has hole in the wall

Room 202 has electrical outlet needing repair

Room 210 has sink top with broken sharp edge needing repair

Room 209 has hole in celling needing repair Room 211 has hole in celling needing repair

Room 212 has hole in ceiling and floor board needing repair

Room 213 has hole in ceiling needing repair

Room 220 has window seal with chipped wood with sharp edge needing repair

Gym had door off hinge needing repair

TA:

Discussed at visit that areas that have peeling paint are being addressed by facility.

Discussed that areas that have holes punched in walls are being addressed by facility.

www.arkansas.gov/dhs Serving more than one million Arkansans each year

7b3da082-528c-e911-b91c-e44cc8a079c4