



Division of Child Care & Early Childhood Education
P.O. Box 1437, Slot S140, Little Rock, AR 72203-1437
P: 501.508.8910 F: 501.683.6060 TDD: 501.682.1550

521 Visit Compliance Report

Licensee: Millcreek of Arkansas PRTF

Facility Number: 233

Licensee Address: 1828 INDUSTRIAL DRIVE
FORDYCE AR 71742

Licensing Specialist: Clayton DeBoer

Person In Charge: Chris Butler

Record Visit Date: 3/17/2023

Home Visit Date: 3/17/2023

Purpose of Visit: Monitor Visit

Regulations Out of Compliance:

Regulation Number: 9. 901. 3

Regulation Description: The agency shall establish and post a written list of children's rights.

Findings Description: No client rights posted in Deerfield.

Action Due Date:

Action Due Description:

Comply Date:

Sub Regulation Description:

Regulation Number: 9. 911. 6

Regulation Description: All buildings and furnishings shall be safe, clean, and in good repair.

Findings Description: Repair issues including flooring, baseboards, shower nozzle and paint in Rock Hill and Pebble Creek.

Action Due Date:

Action Due Description:

Comply Date:

Sub Regulation Description:

Regulations Needing Technical Assistance:

Regulation Not Applicable:

Regulations Not Correctable:

Narrative:

Buildings & Grounds conducted from 10:30AM-12:00PM. Census: 166

Pebble Creek, Rock Hill, Deerfield and Store observed today. Store for faculty use only at this time.

Pebble Creek had no clients present at this time. Clients in school. 1 bathroom shower nozzle was broken leaving 3 additional functioning bathrooms with functioning sinks, showers and toilets. 1 bathroom had scattered spots on the ceiling, the other three bathrooms did not. Sleeping quarters furnished, clean and in good repair.

Rock Hill observed. Bedroom 1 had chipped paint on the walls. Bedroom 2 had flooring that was not laid adjacent to the door hinge, leaving an open area that had collected dirt. Bedroom 4 had a missing baseboard. Bedroom 5 had graffiti on the second shelf of a closet. Bathroom 2 missing shower rings. Flooring in common area had holes throughout.

Deerfield observed. No patient rights could be found posted in Deerfield. Baseboards in bedroom 1 tattered and not connecting. All bedrooms and sleeping quarters observed.

Facility consulted regarding issues found today. Floors in Rock Hill will be contracted out. All other issues to be addressed by facility maintenance. Facility maintenance issues will be prioritized and ready for review on or before 4/3/23. Rock Hill floor repair will depend on contracting schedules. Status of Rock Hill flooring will be reviewed on or before 4/3/23 as well.

MAR checked for:

[REDACTED]
[REDACTED]
[REDACTED]



All initialed and up to date.

Facility cited 901.3 for no posted client rights in Deerfield and 911.6 for multiple repair issues in Rock Hill and Deerfield.

Provider Comments:

CCL Staff Signature :

Date: 3/17/2023

Provider Signature :

Date: 3/17/2023