

Arkansas Department of Human Services
Division of Child Care and Early Childhood Education
 P.O. Box 1437, Slot S140 - Little Rock, AR 72203-1437
 501-682-8590 - Fax: 501-683-8080 - TDD: 501-682-1550

521 Visit Compliance Report

Licensee: Piney Ridge Treatment Center
Licensee Address: 2805 E ZION RD FAYETTEVILLE, AR 72703
Licensing Specialist: Susan L Fancher **Person in Charge:** Adrienne Catalina
Monitor Visit Date: 11/15/2019
Purpose of Visit: Residential Non-Standard Review

Regulations Out of Compliance:

| Regulation | Serious Violation | Discussion/Observation | Due Date | Correction Date | Corrected On Site |
|------------|-------------------|---|------------|-----------------|-------------------|
| R1010.1 | No | loose board on fence needs repaired. | 11/22/2019 | 11/22/2019 | No |
| R1011.7 | No | ceiling tile needs repaired in CL 1, graffiti on bed rails need removed, broken cover on wall in phone room needs repaired. | 12/01/2019 | 11/26/2019 | No |
| R1012.4 | No | Admin bathroom -chipped lid, MPR room-cracked wood trim in bathroom, South Unit-check for mildew substance on ceiling in bathroom, East Unit- rm 2- loose tank cover, rm 6 - wall needs painted where area has been repaired. | 11/15/2019 | 11/15/2019 | No |

Regulations Needing Technical Assistance:

No regulations needing technical assistance.

Regulations Not Correctable:

No regulations marked as not correctable.

Narrative:

www.arkansas.gov/dhs
 Serving more than one million Arkansans each year

9f70c847-f312-ea11-b943-9f1fb6792203

Arkansas Department of Human Services
Division of Child Care and Early Childhood Education
P.O. Box 1437, Slot S140 - Little Rock, AR 72203-1437
501-682-8590 - Fax: 501-683-6060 - TDD: 501-682-1550

Building/Grounds :

viewed all areas accessible to children including four wings, cafeteria, education, outdoor area, classrooms, gym, bathroom and laundry rooms.

Ceiling tile need repair in CL 1, graffiti on bed rails need removed, broken cover on wall in phone room needs repaired

Loose board on wooden fence needs repaired

Admin bathroom-chipped lid

crack in wood trim on bathroom of MPR

South unit- check for mildew substance on ceiling

East unit- Rm 2: has loose tank cover in bathroom, Rm 6- bathroom wall needs painted where repaired with brown spots.

T/A- replaced several pillows w/ torn pillow case.

www.arkansas.gov/dhs
Serving more than one million Arkansans each
year

9f70c647-f312-ea11-b943-0f1fb6792203